ARRET	POWER SUPPLY FOR MOTOR	D.C. FOR LOCAL CIRCUITS TO LINE RELAY AND SEL- ECTOR MAGNETS.	POWER CONNECTIONS
,	110 V. A.C. 50-60 CYCLES	RECT. CONTROL BY PTR. MTR. SWITCH	AS SHOWN
2	110 V. A.C. 50-60 CYCLES	RECTIFIER "ON" CONTINUOUSLY FOR UPPER CASE "H" OR "M" MOTOR CONTROL.	REMOVE WIRE FROM TERM. 3 ON RECEPTAGLE "B" AND CONNECT TO TERM. I.
3	110 V. A.C. 50-60 CYCLES	IIO V. D.C. POWER SUPPLY EXTERNAL TO TABLE (EITHER + OR - GROUNDED)	GONNECT A.G. TO RECEPTAGLE "B" AS SHOWN. REMOVE WIRES FROM + AND - TERMINALS ON RECEPTAGLE "D" AND TAPE ENDS. GONNECT + AND - 110 V. DC. TO CORRESPONDING TERMS. OF RECEPTAGLE "C".
4	IIO V. A.C. 25 CYCLES	RECTIFIER CONTROL BY PTR. MTR. SWITCH	SAME AS ARRGT. I ABOVE EXCEPT ADD 99971 RESISTOR AS SPECIFIED IN NOTE "A" BELOW
5	IIO V. A.C. 25 CYGLES	RECTIFIER "ON" CONTINUOUSLY FOR UPPER CASE "H" OR "M" MOTOR CONTROL	SAME AS ARRGT. 2 ABOVE EXCEPT ADD 99971 RESISTOR AS SPECIFIED IN NOTE "A" BELOW
6	IIO V. A.C. 25 CYCLES	110 V.D.C. POWER SUPPLY EXTERNAL TO TABLE (EITHER + OR- GROUNDED)	SAME AS ARRGT. 3 ABOVE EXCEPT ADD 99971 RESISTOR AS SPECIFIED IN NOTE "A" BELOW
7	110 V.D.C. POWER SUPPLY EXTERNAL TO TABLE (+ GROUNDED)		95050 CORD NOT USED. STRAP PTR. TERMS. 22 & 25. STRAP PTR. TERMS. 23 & 24.
8	110 V.D.C. POWER SUPPLY EXTERNAL TO TABLE (- GROUNDED)		95050 CORD NOT USED. STRAF PTR. TERMS. 22 & 24 . STRAP PTR. TERMS. 23 & 25 .

NOTES:

A. REMOVE AND DISCARD THE STRAP CONNECTED BETWEEN
THE UPPER TERMINAL OF RECEPTAGLE "A" AND TERMINAL
"2 OF RECEPTAGLE "B". REMOVE GROUND LEAD FROM
THE LATTER TERMINAL. CONNECT A LEAD FROM 99971
RESISTOR TO TERMINAL 2 OF RECEPTAGLE "B", AND
CONNECT OTHER RESISTOR LEAD AND GROUND LEAD TO
UPPER TERMINAL OF RECEPTAGLE "A".



